ubawotrk

bjames

Work Order Tracking Report By Requested Date CITY OF MINEOLA

11/06/18

Requested From: 10/01/2018 To: 10/31/2018

Number 008-0009700-001 A BROWN JOHNNY 001-0028300-002 A ELLIOTT-THOMAS HEALTH CTR 006-0005500-001 A MERLINO JOHN R Account Number of work orders: S Customer Name/Address Desc T 211 MC WHORTER STREET 1508 ROBIN 415 W. KILPATRICK 3 Units: N 10292 10247 Number Work 10203 Order Completed: Street Repairs Requested 10/23/18-09:34 10/23/18-09:34 Street Repairs Requested 10/16/18-10:04 10/16/18-10:04 10/17/18-15:42 Street Repairs Requested 10/09/18-08:17 10/09/18-08:17 10/12/18-07:38 Description Field Comment: Field Comment: Cleaned ditch. JM Field Comment: Repaired culvert & patched. BH Instructions: Culvert just E of Dr office is washing out under the roadway Instructions: Repair sink hole where patch is in street Instructions: Culvert is washing out next to mailbox 2 Not Completed: Date/Time Issued Requested Date/Time Completed Date/Time Units Meter Reading 10/17/18 9955609 10/12/18 9957277 Date Number 9956844 Meter 12098625 10156749 12099834 Meter ID Special Page: Special Id 2 Meter