. ubwostrp judy

> W0 Code

BP

CFL

Description

Brush Pickup

Check for Leak

CITY OF MINEOLA	;
Work Order Status Summary Report By Requested Date	
Requested From: 09/01/2019 To: 09/30/2019	Pag
Sorted by Work Order Code Completed Outstanding New	

CO	Change Out Meter	1	1	0
COR	Change Out Register	0	1	1
СР	Check Water Pressure	3	0	0
FR	Final Read	41	0	1
LK	TURN WATER OFF FOR LEAK/REPAIR	3	0	0
LL	Locate Lines	4	0	0
LM	Lock Meter	4	0	0
MI	Miscellaneous	20	2	1
PD	Paid Turn Water Back On	21	0	0
PM	Pull Meter	1	0	0
PML	Pull Meter Log	13	0	0
RR	Re-Read	1	0	0
SB	Sewer Back Up	15	0	0
SM	Set Meter	1	0	0
SR	Start Read	42	0	1
STR	Street Repairs Requested	2	2	2
TWO	Repairs Complete Turn Water On	1	0	0

Report Total:

7

7

Active water accounts: 2,457

Total Meters Read: 2,711

181

10/07/19 11:34 age: 1