ubawotrk bjames

CITY OF MINEOLA
Work Order Tracking Report By Requested Date
Completed From: 02/01/2020 To: 02/29/2020

03/04/20 09:45

004-0021800-000 A CARR EDDIE 003-0002100-004 A POWERS GEORGE E Number Account Number of work orders: -ı v Customer Name/Address Desc 1018 EMILY LANE 102 GOOD STREET 2 Units: Number 13025 Order 12999 Completed: Field Comment: Repaired pot holes at corner of Good & Wigley, and Good & N Pacific. CM Street Repairs Requested 02/18/20-07:48 02/18/20-07:48 02/18/20-11:01 1 Street Repairs Requested 02/12/20-07:58 02/12/20-07:58 02/18/20-11:01 Description Work Order Field Comment: Repaired Pot Hole. CM Instructions: Repair Pot Hole Instructions: Repair pot holes at corner of Good & Wigley, and Good & N Pacific Not Completed: Date/Time Issued Requested Date/Time Date/Time Completed Units Meter Reading 02/18/20 9956935 02/18/20 9957140 Date Number Meter 12094311 Meter ID 12099750 Special Page: Special Id 2 Meter