## ubawotrk bjames

CITY OF MINEOLA
Work Order Tracking Report By Requested Date
Completed From: 06/01/2020 To: 06/30/2020

	e
8	7
ü	5
ū	2

007-0013500-002 A ROYAL LOUISE 010-0012800-000 A RIDDLE WELDON 007-0015730-000 A ADDIE MCFARLAND FOUNDATION Number 004-0022000-000 A DAWSON D. R. Account Number of work orders: - v Customer Name/Address Desc 507 SOUTH STREET 504 WREN 708 STONE 1026 EMILY LANE 4 Units: 13488 Number 0rder 13485 13398 Work 13500 Completed: Street Repairs Requested 05/29/20-15:37 05/29/20-15:37 06/18/20-09:46 Street Repairs Requested 05/05/20-14:46 05/05/20-14:46 06/30/20-16:12 Street Repairs Requested 06/04/20-10:03 06/04/20-10:03 06/19/20-14:58 Street Repairs Requested 05/28/20-13:09 05/28/20-13:09 06/26/20-11:44 Description Field Comment: Repaired sink hole at edge of property line at telephone pole. MH Instructions: Customer is requesting the ditch to be cleaned in front of his house, like they cleaned the ditch ac Field Comment: Charlie, mark, and willie put a load of base and 6 tons of asphalt Field Comment: Repaired pot holes at the intersection of Boundry & Belcher near McFarland School. Put 60 tons aspha Instructions: Repair sink hole at edge of property line at telephone pole. Field Comment: cleaned the ditch Instructions: Pot holes at the intersection of Boundry & Belcher near McFarland School. Instructions: Customer said the road was caving in just E of his house. It at the intersection. CM Not Completed: ross the street: customer talked to William Crump and he told him to call to request a WO. Date/Time Issued 0 Requested Date/Time Completed Date/Time Units Meter Reading 06/18/20 9957303 12099276 06/26/20 9955446 06/19/20 9955570 06/30/20 8398580 Date Read Number Meter 10204464 10148193 10297261 Meter ID Special Page: Id 2 Special Meter