ubawotrk bjames

CITY OF MINEOLA Work Order Tracking Report By Requested Date 12/02/20

13:55

Completed From: 11/01/2020 To: 11/30/2020 Page: Account S Customer Name/Address Desc Work Work Order Date/Time Date/Time Date/Time Units Meter Meter Special Number Order Description Issued Requested Completed Reading Date Number Meter ID Meter Number Id 2 002-0003600-031 A MAXWELL DONALD 14190 Street Repairs Requested 10/26/20-13:29 10/26/20-13:29 11/16/20-09:02 11/16/20 10474273 10699892 506 HOGG Instructions: Customer says that after the big leak on Hogg and Buchanan, they left mud on Patten and Buchanan. He is requesting the street to be cleaned Field Comment: 005-0026600-001 A CHURCHILL VIRGINIA 14256 Street Repairs Requested 11/09/20-11:10 11/09/20-11:10 11/13/20-14:13 10708638 11/13/20 10474364 215 SPRING LAKE Instructions: Customer requested that we clean rock & gravel that has washed around her mail box. Field Comment: Cleaned street. RS 009-0008000-001 A HIGGINBOTHAM BROS., & CO., LLC 14358 Street Repairs Requested 11/23/20-16:31 11/23/20-16:31 11/23/20-16:33 1 11/23/20 9568725 12098859 401 S. PACIFIC Instructions: DISPATCH CALLED AND REQUESTED SOMEONE FROM STREET DEPT GO GET SOME FARM EQUIP IN THE MIDDLE OF S. 69 ACROSS THE TRACKS. CALLED SKIP AND HE IS ON THE WAY Field Comment: Number of work orders: 3 Units: Completed: 3 Not Completed: