ubawotrk

Work Order Tracking Report By Requested Date CITY OF MINEOLA

03/01/21

b j ames Number 004-0013000-002 A WARD KIMBERLY A 010-0000400-002 A THE WORKS 008-0009800-008 A JONES GRAYLING 005-0026800-002 A HOWARD TROY Account Number of work orders: - v Customer Name/Address Desc 314 E. BROAD 210 MC WHORTER STREET 219 SPRING LAKE 133 CIRCLE DR. 4 Units: 14695 Number 0rder 14974 14734 13860 Completed: Street Repairs Requested 02/22/21-15:34 02/22/21-15:34 02/24/21-09:53 Street Repairs Requested 01/28/21-15:50 01/28/21-15:50 02/24/21-15:52 Street Repairs Requested 02/04/21-14:26 02/04/21-14:26 02/26/21-10:29 Street Repairs Requested 08/21/20-08:36 08/21/20-08:36 02/25/21-16:14 Description Field Comment: put fillings on the alley behind their house Field Comment: put asphalt Instructions: customer requested street repairs (pot hole) on the street that is on the East Side of their place. Field Comment: Put asphalt to repair drive way entrance. Customer installed culvert. CM Field Comment: Put asphalt to repair pot holes. CM Instructions: Need to repair driveway entrance where customer installed a culvert. Instructions: Pot holes in front of house & around mail box Instructions: customer requested repairs in the alley behind her house. She said the dirt washed out and there are Completed From: 02/01/2021 To: 02/28/2021 4 Not Completed: she says is not private property. pot holes. Date/Time Issued Requested Date/Time Completed Date/Time Units Meter Reading 02/26/21 9957341 02/24/21 7877167 02/24/21 02/25/21 8226393 Date 20229337 Number Meter 10263329 10473888 12100585 10452682 Meter ID Special Page: Special Id 2 Meter