

MEMORANDUM

DATE: March 25, 2022
TO: Mayor Lankford & City Council
VIA: Mercy Rushing, City Manager
FROM: Doris Newman, Main Street Manager
SUBJECT: Museum sewer backup

On Monday morning, Feb. 28, less than a week after our Chick Fil A fundraiser and five days before our Black History Month Quilt Program, Sharon Chamblee reported the museum basement was flooded with 6" of sewer water. (I took attached photos of inside the basement and also the exterior basement door at the bottom of the stairwell on the south side of the building. On this you can see how high the water is on the door kickplate.) Public Works Director William Crump and a helper found that the sewer pump had no power to it. We had had an electrical outage in part of town over that weekend. William connected a generator to pump the sewer water out of the basement, channeling downhill it to the manhole and sewer line in the alley. He estimated it would take a couple of days to get the water out and to be able to go in to assess the problem. Approximately two days later the majority of the water was removed, he was able to go in and assess that the motor to the pump needed replacing.

ServPro Restoration Services was called. City Secretary Cindy Karch notified our insurer, TML. Their adjustor and ServPro personnel met with Justin Clower and myself on March 8. Water still remained on the floor in several areas and ServPro brought in their generator, air mover, dehumidifier and two storage pods where items that could be salvaged were placed in while the basement and contents were purged of the sewer water and gas, cleaned and sanitized with an anti-microbial agent on every surface.

Fortunately, the majority of items were stored on top of three pallets and/or inside plastic tubs or set on top of tables so it appeared the loss wouldn't be as great as initially feared. That included our archives that are on rolling racks and some stacked tables. Those tables were moved to allow the floor to be cleaned and table legs as well. The Museum was open its normal days during this and we were fortunate that we experienced some cold weather that prevented the situation from being worse than it already was.

The pallets on which things were stacked three-high were the bulk of our loss. With the water as high as it was, it also wicked up to levels that weren't in the water. Only 20 pallets were salvageable. A stove and refrigerator in the lunchroom which had been standing in the water were removed.

The cleaning, sanitizing process was completed by Wednesday, March 16. Justin received a donation of 40 pallets from Woodshed Truss and transported those to the museum, unloading them for us with assistance of the ServPro workers. The workers assistance our museum staff in returning items to the pallets and this past Wednesday, March 23, the pods were removed from the Museum parking lot.

Note: The ServPro service was topnotch, profession and friendly. William and his crew and Justin with his assistance were invaluable in this process. Mercy's and Cindy's advice and support were a huge help. And we're extremely grateful for Sharon Chamblee and her helpers for placing our historic items and decorations out of harm's way, preventing the damage from being any worse that it was.




Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



1

Date Taken: 3/8/2022

Exterior



2

Date Taken: 3/8/2022

Exterior

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842


Policy #: 5727



3

Date Taken: 3/8/2022

Exterior



BigStorageRoom - 4

Date Taken: 3/8/2022

Stairs

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BigStorageRoom - 5

Date Taken: 3/8/2022

Overview



BigStorageRoom - 6

Date Taken: 3/8/2022

Overview

Photo Sheet


JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BigStorageRoom - 7

Date Taken: 3/8/2022

Overview



BigStorageRoom - 8

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BigStorageRoom - 9

Date Taken: 3/8/2022

Overview



BigStorageRoom - 10

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BigStorageRoom - 11

Date Taken: 3/8/2022

Water on ground-Middle of room



BigStorageRoom - 12

Date Taken: 3/8/2022

Bathroom

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



SuppliesCloset - 13

Date Taken: 3/8/2022

Overview



SuppliesCloset - 14

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842


Policy #: 5727



SuppliesCloset - 15

Date Taken: 3/8/2022

Overview



SuppliesCloset - 16

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842


Policy #: 5727



SuppliesCloset - 17

Date Taken: 3/8/2022

Water on ground



UnitBStorage - 18

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



UnitBStorage - 19

Date Taken: 3/8/2022

Overview



UnitBStorage - 20

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



UnitBStorage - 21

Date Taken: 3/8/2022

Overview



ToyRoom - 22

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842


Policy #: 5727



ToyRoom - 23

Date Taken: 3/8/2022

Overview



BreakRoom - 24

Date Taken: 3/8/2022

Water damage to door and jamb/casing

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BreakRoom - 25

Date Taken: 3/8/2022

Water damage to door and jamb/casing



BreakRoom - 26

Date Taken: 3/8/2022

Water damage to door and jamb/casing

Photo Sheet


JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BreakRoom - 27

Date Taken: 3/8/2022

Water damage to door and jamb/casing



BreakRoom - 28

Date Taken: 3/8/2022

Water damage to door and jamb/casing

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BreakRoom - 29

Date Taken: 3/8/2022

Overview



BreakRoom - 30

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842


Policy #: 5727



BreakRoom - 31

Date Taken: 3/8/2022

Overview



BreakRoom - 32

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BreakRoom - 33

Date Taken: 3/8/2022

Cabinet overview



BreakRoom - 34

Date Taken: 3/8/2022

Water damage to toe kick

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BreakRoom - 35

Date Taken: 3/8/2022

Water damage to toe kick



BreakRoom - 36

Date Taken: 3/8/2022

Swelling to end panel

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842


Policy #: 5727



BreakRoom - 37

Date Taken: 3/8/2022

Swelling to end panel



BreakRoom - 38

Date Taken: 3/8/2022

Swelling to end panel

Photo Sheet


JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BreakRoom - 39

Date Taken: 3/8/2022

Fridge not working



BreakRoom - 40

Date Taken: 3/8/2022

Fridge overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842


Policy #: 5727



BreakRoom - 41

Date Taken: 3/8/2022

Fridge overview



BreakRoom - 42

Date Taken: 3/8/2022

Model # 253.60412614/Type: AD-18

Manufacture Date: 08/2017

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



BreakRoom - 43

Date Taken: 3/8/2022

Oven working



Hallway - 44

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Hallway - 45

Date Taken: 3/8/2022

Overview



Hallway Bathrooms - 46

Date Taken: 3/8/2022

Women overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



HallwayBathrooms - 47

Date Taken: 3/8/2022

Women overview



HallwayBathrooms - 48

Date Taken: 3/8/2022

Women overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



HallwayBathrooms - 49

Date Taken: 3/8/2022

Women overview



HallwayBathrooms - 50

Date Taken: 3/8/2022

Men overview

Photo Sheet


JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Hallway Bathrooms - 51

Date Taken: 3/8/2022

Men overview



Hallway Bathrooms - 52

Date Taken: 3/8/2022

Men overview

Photo Sheet


JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Hallway Bathrooms - 53

Date Taken: 3/8/2022

Water damage to door casings



ArtRoom - 54

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



ArtRoom - 55

Date Taken: 3/8/2022

Overview



ArtRoom - 56

Date Taken: 3/8/2022

Overview-Water on ground

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



ArtRoom - 57

Date Taken: 3/8/2022

Overview



ArtRoom - 58

Date Taken: 3/8/2022

Water soaked studs

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



ArtRoom - 59

Date Taken: 3/8/2022

Water soaked studs



ArtRoom - 60

Date Taken: 3/8/2022

Water soaked studs

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



ArtRoom - 61

Date Taken: 3/8/2022

Water soaked studs



ArtRoom - 62

Date Taken: 3/8/2022

Water soaked studs

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842


Policy #: 5727



ArtRoom - 63

Date Taken: 3/8/2022

Water damage to door



ArtRoom - 64

Date Taken: 3/8/2022

Water damage to door

Photo Sheet


JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842


Policy #: 5727



FramingRoom - 65

Date Taken: 3/8/2022

Overview



FramingRoom - 66

Date Taken: 3/8/2022

Overview-Water on ground

Photo Sheet


JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



FramingRoom - 67

Date Taken: 3/8/2022

Overview



FramingRoom - 68

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



FramingRoom - 69

Date Taken: 3/8/2022

Overview



FramingRoom - 70

Date Taken: 3/8/2022

Water soaked studs

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



FramingRoom - 71

Date Taken: 3/8/2022

Water soaked studs



FramingRoom - 72

Date Taken: 3/8/2022

Water soaked studs

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



DocumentRoom - 73

Date Taken: 3/8/2022

Overview



DocumentRoom - 74

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



DocumentRoom - 75

Date Taken: 3/8/2022

Overview



DocumentRoom - 76

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



DocumentRoom - 77

Date Taken: 3/8/2022

Overview-Water on ground



DocumentRoom - 78

Date Taken: 3/8/2022

Water soaked studs

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



DocumentRoom - 79

Date Taken: 3/8/2022

Water soaked studs



DocumentRoom - 80

Date Taken: 3/8/2022

Water soaked studs

Photo Sheet


JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



LumberRoom - 81

Date Taken: 3/8/2022

Overview



LumberRoom - 82

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



LumberRoom - 83

Date Taken: 3/8/2022

Overview



LumberRoom - 84

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



LumberRoom - 85

Date Taken: 3/8/2022

Overview-Water on ground



LumberRoom - 86

Date Taken: 3/8/2022

Overview

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Content - 87

Date Taken: 3/8/2022

All base pallets water damaged



Content - 88

Date Taken: 3/8/2022

All base pallets water damaged

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Content - 89

Date Taken: 3/8/2022

All base pallets water damaged



Content - 90

Date Taken: 3/8/2022

All base pallets water damaged

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Content - 91

Date Taken: 3/8/2022

Metal legs on tables rusting



Content - 92

Date Taken: 3/8/2022

Metal legs on tables rusting

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Content - 93

Date Taken: 3/8/2022

Metal legs on tables rusting



Content - 94

Date Taken: 3/8/2022

Metal legs on tables rusting

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Content - 95

Date Taken: 3/8/2022

Metal legs on tables rusting



Content - 96

Date Taken: 3/8/2022

Metal legs on tables rusting

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Content - 97

Date Taken: 3/8/2022

Metal legs on tables rusting



Content - 98

Date Taken: 3/8/2022

Metal legs on tables rusting

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Content - 99

Date Taken: 3/8/2022

Metal legs on tables rusting



Content - 100

Date Taken: 3/8/2022

Metal legs on tables rusting

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Content - 101

Date Taken: 3/8/2022

Metal legs on tables rusting



Content - 102

Date Taken: 3/8/2022

Metal legs on tables rusting

Photo Sheet

JT Parker Claims

P.O. Box 6233
Longview, TX 75608
903-753-3950 Office
903-753-5514 Fax

Insured: City of Mineola

Claim #: PR164842

Policy #: 5727



Content - 103

Date Taken: 3/8/2022

Metal legs on tables rusting



Content - 104

Date Taken: 3/8/2022

Metal legs on tables rusting

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
2436 Peyton Rd. Houston, TX 77032
(903) 561-0168
Servpro8780@servprooftyler.com
Tax ID # 87-3324522

Client: Mineola Historic Museum
Property: 114 N Pacific St
Mineola, TX 75773

Home: (903) 705-3399

Operator: ADMIN4

Estimator: Jill Furlow
Business: 20958 FM 2493
Bullard, TX 75757

Business: (903) 561-0168
E-mail: admin4@servprooftyler.com

Type of Estimate: Water Damage

Date Entered: 3/4/2022

Date Assigned: 3/3/2022

Price List: TXY8X_MAR22

Labor Efficiency: Restoration/Service/Remodel

Estimate: MINEOLA_MUSEUM

**Based upon our initial inspection the following is our estimated cost to complete the work requested. This estimate is not a contract or a bill. If additional work is required, the total cost of the following estimate is subject to change. By accepting the estimate, and requesting work to be performed, the above statements are acknowledged. Please remember this is only an estimate and is subject to change based on actual work performed. Please let us know if you have any questions. This estimate is good for 30 days from the date entered.

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
 2436 Peyton Rd. Houston, TX 77032
 (903) 561-0168
 Servpro8780@servprooftyler.com
 Tax ID # 87-3324522

MINEOLA_MUSEUM

Main Level

Job Tab

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
1. Cleaning & Remediation - Supervisory - per hr	24.00 HR	0.00	53.66	106.25	1,394.09
1 supervisor for 8 hours/day for 3 days = 24 Total 24					
2. Personal protective mask (N-95)	12.00 EA	0.00	3.23	3.20	41.96
3. Personal protective gloves - Disposable (per pair)	12.00 EA	0.00	0.32	0.32	4.16
4. Pod Rental 12' X 2	1.00 EA	0.00	1,043.54	86.09	1,129.63
5. Content Manipulation charge - per hour	24.00 HR	0.00	38.54	76.31	1,001.27
Moving of items estimated for 3 days with 2 crews = 24 hours					
Totals: Job Tab				272.17	3,571.11
Total: Main Level				272.17	3,571.11
Line Item Totals: MINEOLA_MUSEUM				272.17	3,571.11

Grand Total Areas:

7,217.17 SF Walls	3,591.91 SF Ceiling	10,809.08 SF Walls and Ceiling
3,591.91 SF Floor	399.10 SY Flooring	833.33 LF Floor Perimeter
0.00 SF Long Wall	0.00 SF Short Wall	833.33 LF Ceil. Perimeter
3,591.91 Floor Area	3,875.02 Total Area	7,217.17 Interior Wall Area
8,357.17 Exterior Wall Area	865.33 Exterior Perimeter of Walls	
0.00 Surface Area	0.00 Number of Squares	0.00 Total Perimeter Length
0.00 Total Ridge Length	0.00 Total Hip Length	

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
2436 Peyton Rd. Houston, TX 77032
(903) 561-0168
Servpro8780@servprooftyler.com
Tax ID # 87-3324522

Summary for Dwelling

Line Item Total	3,298.94
Comm. Rpr/Remdl Tax	272.17
Replacement Cost Value	\$3,571.11
Net Claim	\$3,571.11

Jill Furlow

**Based upon our initial inspection the following is our estimated cost to complete the work requested. This estimate is not a contract or a bill. If additional work is required, the total cost of the following estimate is subject to change. By accepting the estimate, and requesting work to be performed, the above statements are acknowledged. Please remember this is only an estimate and is subject to change based on actual work performed. Please let us know if you have any questions. This estimate is good for 30 days from the date entered.

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
2436 Peyton Rd. Houston, TX 77032
(903) 561-0168
Servpro8780@servprooftyler.com
Tax ID # 87-3324522

Client: Mineola Historic Museum
Property: 114 N Pacific St
Mineola, TX 75773

Home: (903) 705-3399

Operator: ADMIN4

Estimator: Jill Furlow
Business: 20958 FM 2493
Bullard, TX 75757

Business: (903) 561-0168
E-mail: admin4@servprooftyler.com

Type of Estimate: Water Damage

Date Entered: 3/4/2022

Date Assigned: 3/3/2022

Price List: TXY8X_MAR22

Labor Efficiency: Restoration/Service/Remodel

Estimate: MINEOLA_MUSEUM-1

**Based upon our initial inspection the following is our estimated cost to complete the work requested. This estimate is not a contract or a bill. If additional work is required, the total cost of the following estimate is subject to change. By accepting the estimate, and requesting work to be performed, the above statements are acknowledged. Please remember this is only an estimate and is subject to change based on actual work performed. Please let us know if you have any questions. This estimate is good for 30 days from the date entered.

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
 2436 Peyton Rd. Houston, TX 77032
 (903) 561-0168
 Servpro8780@servprooftyler.com
 Tax ID # 87-3324522

MINEOLA_MUSEUM-1


Main Level

Job Tab

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
1. Emergency service call - during business hours	1.00 EA	0.00	143.09	11.80	154.89
2. Cleaning & Remediation - Supervisory - per hr	15.00 HR	0.00	53.66	66.40	871.30
1 supervisor for 3 hours/day for 5 days = 15 Total 15					
3. Equipment setup, take down, and monitoring (hourly charge)	7.50 HR	0.00	51.35	31.77	416.90
Set up 1.5 Monitor 1.5 Monitor 1.5 Monitor 1.5 Monitor and take down 1.5 Total 7.5					
4. Personal protective mask (N-95)	20.00 EA	0.00	3.23	5.33	69.93
5. Personal protective gloves - Disposable (per pair)	20.00 EA	0.00	0.32	0.53	6.93
6. Air mover (per 24 hour period) - No monitoring	30.00 EA	0.00	26.14	64.70	848.90
7. Dehumidifier (per 24 hour period) - No monitoring	50.00 EA	0.00	58.24	240.24	3,152.24
8. Neg. air fan/Air scrub.-Large (per 24 hr period)-No monit.	15.00 DA	0.00	105.00	129.94	1,704.94
9. Add for HEPA filter (for negative air exhaust fan)	3.00 EA	0.00	193.97	48.01	629.92
Totals: Job Tab				598.72	7,855.95

Art Supply Room

Height: 8'



328.00 SF Walls	96.06 SF Ceiling
424.06 SF Walls & Ceiling	96.06 SF Floor
10.67 SY Flooring	41.00 LF Floor Perimeter
41.00 LF Ceil. Perimeter	


DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
10. Apply anti-microbial agent to the floor	96.06 SF	0.00	0.25	1.98	26.00

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
 2436 Peyton Rd. Houston, TX 77032
 (903) 561-0168
 Servpro8780@servprooftyler.com
 Tax ID # 87-3324522


CONTINUED - Art Supply Room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
11. Clean floor	96.06 SF	0.00	0.42	3.33	43.68
Totals: Art Supply Room				5.31	69.68



Big Storage Room				Height: 9'	
1,008.00 SF Walls				763.75 SF Ceiling	
1,771.75 SF Walls & Ceiling				763.75 SF Floor	
84.86 SY Flooring				112.00 LF Floor Perimeter	
112.00 LF Ceil. Perimeter					

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
12. Apply anti-microbial agent to the floor	763.75 SF	0.00	0.25	15.75	206.69
13. Clean floor	763.75 SF	0.00	0.42	26.46	347.24
Totals: Big Storage Room				42.21	553.93




Break Room				Height: 8'	
490.67 SF Walls				232.60 SF Ceiling	
723.27 SF Walls & Ceiling				232.60 SF Floor	
25.84 SY Flooring				61.33 LF Floor Perimeter	
61.33 LF Ceil. Perimeter					

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
14. Apply anti-microbial agent to the floor	232.60 SF	0.00	0.25	4.80	62.95
15. Clean floor	232.60 SF	0.00	0.42	8.06	105.75
Totals: Break Room				12.86	168.70

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
 2436 Peyton Rd. Houston, TX 77032
 (903) 561-0168
 Servpro8780@servprooftyler.com
 Tax ID # 87-3324522




Document Room

Height: 8'

785.33 SF Walls	480.38 SF Ceiling
1,265.71 SF Walls & Ceiling	480.38 SF Floor
53.38 SY Flooring	98.17 LF Floor Perimeter
98.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
16. Apply anti-microbial agent to the floor	480.38 SF	0.00	0.25	9.91	130.01
17. Clean floor	480.38 SF	0.00	0.42	16.65	218.41
Totals: Document Room				26.56	348.42




Framing Room

Height: 8'

334.67 SF Walls	99.08 SF Ceiling
433.75 SF Walls & Ceiling	99.08 SF Floor
11.01 SY Flooring	41.83 LF Floor Perimeter
41.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
18. Apply anti-microbial agent to the floor	99.08 SF	0.00	0.25	2.04	26.81
19. Clean floor	99.08 SF	0.00	0.42	3.43	45.04
Totals: Framing Room				5.47	71.85



Hall 2

Height: 8'

324.00 SF Walls	75.39 SF Ceiling
399.39 SF Walls & Ceiling	75.39 SF Floor
8.38 SY Flooring	40.50 LF Floor Perimeter
40.50 LF Ceil. Perimeter	

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
20. Apply anti-microbial agent to the floor	75.39 SF	0.00	0.25	1.56	20.41

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
 2436 Peyton Rd. Houston, TX 77032
 (903) 561-0168
 Servpro8780@servprooftyler.com
 Tax ID # 87-3324522

CONTINUED - Hall 2

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
21. Clean floor	75.39 SF	0.00	0.42	2.61	34.27
Totals: Hall 2				4.17	54.68


Hallway

Height: 9'



595.50 SF Walls	134.58 SF Ceiling
730.08 SF Walls & Ceiling	134.58 SF Floor
14.95 SY Flooring	66.17 LF Floor Perimeter
66.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
22. Apply anti-microbial agent to the floor	134.58 SF	0.00	0.25	2.78	36.43
23. Clean floor	134.58 SF	0.00	0.42	4.66	61.18
Totals: Hallway				7.44	97.61



Lumber Room


Height: 9'

837.00 SF Walls	530.00 SF Ceiling
1,367.00 SF Walls & Ceiling	530.00 SF Floor
58.89 SY Flooring	93.00 LF Floor Perimeter
93.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
24. Apply anti-microbial agent to the floor	530.00 SF	0.00	0.25	10.93	143.43
25. Clean floor	530.00 SF	0.00	0.42	18.36	240.96
Totals: Lumber Room				29.29	384.39

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
 2436 Peyton Rd. Houston, TX 77032
 (903) 561-0168
 Servpro8780@servprooftyler.com
 Tax ID # 87-3324522




Storage Room

Height: 9'

694.50 SF Walls	343.28 SF Ceiling
1,037.78 SF Walls & Ceiling	343.28 SF Floor
38.14 SY Flooring	77.17 LF Floor Perimeter
77.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
26. Apply anti-microbial agent to the floor	343.28 SF	0.00	0.25	7.08	92.90
27. Clean floor	343.28 SF	0.00	0.42	11.89	156.07
Totals: Storage Room				18.97	248.97




Supplies Closet

Height: 9'

630.00 SF Walls	298.69 SF Ceiling
928.69 SF Walls & Ceiling	298.69 SF Floor
33.19 SY Flooring	70.00 LF Floor Perimeter
70.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
28. Apply anti-microbial agent to the floor	298.69 SF	0.00	0.25	6.16	80.83
29. Clean floor	298.69 SF	0.00	0.42	10.35	135.80
Totals: Supplies Closet				16.51	216.63



Toy Room

Height: 9'

553.50 SF Walls	234.01 SF Ceiling
787.51 SF Walls & Ceiling	234.01 SF Floor
26.00 SY Flooring	61.50 LF Floor Perimeter
61.50 LF Ceil. Perimeter	


DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
30. Apply anti-microbial agent to the floor	234.01 SF	0.00	0.25	4.83	63.33

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
 2436 Peyton Rd. Houston, TX 77032
 (903) 561-0168
 Servpro8780@servprooftyler.com
 Tax ID # 87-3324522

CONTINUED - Toy Room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
31. Clean floor	234.01 SF	0.00	0.42	8.11	106.39
Totals: Toy Room				12.94	169.72



Unit B Storage

Height: 9'

636.00 SF Walls	304.08 SF Ceiling
940.08 SF Walls & Ceiling	304.08 SF Floor
33.79 SY Flooring	70.67 LF Floor Perimeter
70.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
32. Apply anti-microbial agent to the floor	304.08 SF	0.00	0.25	6.27	82.29
33. Clean floor	304.08 SF	0.00	0.42	10.54	138.25
Totals: Unit B Storage				16.81	220.54
Total: Main Level				797.26	10,461.07
Line Item Totals: MINEOLA_MUSEUM-1				797.26	10,461.07

Grand Total Areas:

7,217.17 SF Walls	3,591.91 SF Ceiling	10,809.08 SF Walls and Ceiling
3,591.91 SF Floor	399.10 SY Flooring	833.33 LF Floor Perimeter
0.00 SF Long Wall	0.00 SF Short Wall	833.33 LF Ceil. Perimeter
3,591.91 Floor Area	3,875.02 Total Area	7,217.17 Interior Wall Area
8,357.17 Exterior Wall Area	865.33 Exterior Perimeter of Walls	
0.00 Surface Area	0.00 Number of Squares	0.00 Total Perimeter Length
0.00 Total Ridge Length	0.00 Total Hip Length	

SERVPRO of Lindale/ North Smith County

SERVPRO of Lindale/ North Smith County #11615
2436 Peyton Rd. Houston, TX 77032
(903) 561-0168
Servpro8780@servprooftyler.com
Tax ID # 87-3324522

Summary for Dwelling

Line Item Total	9,663.81
Comm. Rpr/Remdl Tax	797.26
Replacement Cost Value	\$10,461.07
Net Claim	\$10,461.07

Jill Furlow

**Based upon our initial inspection the following is our estimated cost to complete the work requested. This estimate is not a contract or a bill. If additional work is required, the total cost of the following estimate is subject to change. By accepting the estimate, and requesting work to be performed, the above statements are acknowledged. Please remember this is only an estimate and is subject to change based on actual work performed. Please let us know if you have any questions. This estimate is good for 30 days from the date entered.