

PUBLIC WORKS

October (9/11-10/22)

Wastewater

- Normal ground maintenance & lab work
- New baffle/wall installed in the new UV system
- Water department dug up and fixed 2” water line at the plant
- Drive assembly is working again at the headworks
- Quarterly biomonitoring results came back and we passed